

# Ford/Lincoln/Mercury

## Bumper Fascia Fastener Kit Application Chart

Vehicle	Model Year	Application	Part Number	Parts in Kit	List Price
Crown Victoria	95/97	Front	3W7Z-17C756-BA	50	\$ 25.26
Crown Victoria	00/04	Rear	3W7Z-17C756-AA	48	\$ 21.05
Mustang	94/95	Front	3R3Z-17C756-DA	43	\$ 25.30
Mustang	94/95	Rear	3R3Z-17C756-BA	43	\$ 21.08
Mustang	99/01	Rear	3R3Z-17C756-AA	36	\$ 18.27
Mustang	00/04	Front	3R3Z-17C756-CA	58	\$ 25.30
Explorer	98	Front	3L2Z-17C756-AA	54	\$ 21.92
Grand Marquis	92/94	Front	3W3Z-17C756-AA	79	\$ 25.26
Taurus/Sable	92/95	Front	3F1Z-17C756-BA	28	\$ 29.92
Taurus/Sable	92/95	Rear	3F1Z-17C756-AA	29	\$ 24.93
Taurus	96/99	Rear	3F1Z-17C756-DA	60	\$ 29.92
Taurus/Sable	98/99	Front	3F1Z-17C756-CA	31	\$ 29.92
Thunderbird	94/95	Front	3F6Z-17C756-AA	47	\$ 29.92
Town Car	95/97	Front	3W1Z-17C756-BA	63	\$ 25.26
Town Car	98/02	Front	3W1Z-17C756-AA	45	\$ 25.26
Windstar	95/98	Rear	3F2Z-17C756-BA	31	\$ 29.92
Windstar	95/97	Front	3F2Z-17C756-AA	66	\$ 29.92

# Ford/Lincoln/Mercury

## Technical Service Bulletin Information

<b>TSB #</b>	<b>Vehicle(s)</b>	<b>Model Year(s)</b>	<b>Issue</b>
03-3-7	Multiple	2002-2003	No blending clearcoat
03-10-1	Multiple	2002-2003	Proper paint preparation for plastic fascias
03-15-4	F-150	2004	Instrument panel scratch/mar repair tips
03-25-5	Mustang	2001-2004	Hood paint pin hole repair
04-2-5	F-150	2004	Magnesium core support handling & repair

**Copies Available on Back Table**